




## Stanley 1913 Recalls Switchback and Trigger Action Travel Mugs Due to Burn Hazard

Stanley 1913 announced a voluntarily recall of certain Switchback and Trigger Action Travel Mugs because the lid threads can shrink when exposed to heat and torque, causing the lid to detach during use, posing a burn hazard.

The products affected include:

Name	Size	Product Identification Number
<b>Switchback</b> 	354ml / 12oz	20-01437, 20-02363
	384ml / 13oz	20-02363
	473ml / 16oz	20-01436, 20-02354, 20-02211
<b>Trigger Action</b> 	250ml / 8.5oz	20-02824
	354ml / 12oz (slim)	20-02825, 20-02779
	354ml / 12oz	20-02454, 20-02033
	473ml / 16oz	20-02957, 20-02030, 20-02745, 20-02453
	591ml / 20oz	20-02746, 20-02034

The product identification number is located on the bottom of the mug:



Consumers currently in possession of the affected Switchback or Trigger Action travel mugs should immediately stop using these products. To determine if your product is impacted and to request a free replacement lid, please enter your product identification number at this [website](#). This will also begin the compensation selection process.