

Versuni (licensee of the brand PHILIPS) Recalls Philips Perfect Care 8000, 9000, and Elite series Pressurized Steam Generator Irons

Versuni has issued a voluntary recall for the Philips Pressurized Steam Generator Irons models starting with PSG8, GC96 and PSG90, and code numbers 2421, 2422 or 2423.

This recall has been initiated due to a manufacturing issue in the welding of the boiler that generates the steam in the steam system, which may result in injuries like burns or impact-related injuries.

To determine whether your unit is impacted, and begin the compensation selection process, enter your device serial number at this [link](#).

Please see below as reference for how to locate the serial number on your product:



Consumers in possession of the affected units should immediately stop using the steam generating iron, and unplug it from the power outlet.

For more assistance, please contact +65 800 8528285 (Mon – Fri 0900 - 1800) or Whatsapp: +65 63119130 (Mon – Sun 0900 – 1800).